

Oil Field Environmental Incident Summary

Incident: 20160802200711 **Date/Time of Notice:** 08/02/2016 20:07

Responsible Party: WHITE ROCK OIL & GAS, LLC

Well Operator: WHITE ROCK OIL & GAS, LLC

Well Name: BIG STICK (MADISON) UNIT 2001

Field Name: BIG STICK

Well File #: 6756

Date Incident: 8/2/2016 **Time Incident:** 16:00

Facility ID Number:

County: BILLINGS

Twp: 142

Rng: 100

Sec: 20

Qtr:

Location Description:

Submitted By: Travis White

Received By:

Contact Person: Travis White
5001 SPRING VALLEY RD
SUITE 100 E.
DALLAS, TX 75244

General Land Use: Badlands Terrain

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pipeline Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	1	Barrels			1	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 8/18/2016

Clean Up Concluded: 8/12/2016

Risk Evaluation:

Minimal

Areal Extent:

Bubbled to surface at source of leak.

Potential Environmental Impacts:

No impact to surface water; only impact to localized vegetation.

Action Taken or Planned:

Isolated line and excavate soil to source of flowline. Replace line, dispose contaminated soil to proper facility, and replace excavated soil.

Wastes Disposal Location: R360

Agencies Involved:

Updates

Date: 8/3/2016 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release was not contained. Further follow-up needed.

Date: 8/16/2016 **Status:** Inspection

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 1330. GPS coordinates to this release are: 47.11025 -103.3858. The pipeline release started on top of the hill and appears to have run down the hill and possibly into a drainage. I tested the water for chlorides and got a non-detect. At the top of the hill the pipeline is exposed. A large gully with dead vegetation is visible from the point of the release all the way to the drainage. Further follow-up is needed on cleanup. Photos can be found in the report folder.